OAHP Site #: 5GF.5900 OAHP Form #1417

COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP *Historical / Architectural Properties: Intensive Level / Evaluation* form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)				
Date:	Initials:			
□ Determined Elig□ Determined Elig	•			
□ Needs Data				
☐ Eligible District	- Contributing			

IDENTIFICATION

1. Property Name:	Smith Residen	<u>ce</u>		\boxtimes H	istoric	☐ Curren	t 🗆 Othe	r:
2. Resource Class	ification: 🛛 🖾 I	Building	☐ Structure	□ Object	□ 8	Sites/Landso	cape	
3. Ownership:	☐ Federal	☐ State	☐ Local	☐ Non-pro	fit 🗵 F	Private	□ Unknown	ı
LOCATION								
4. Street Address:	644 West Main	Street						
5. Municipality: Ne	ew Castle, CO			☐ Vicinity:				
6. County: Garfield	[**Please ch	eck with your project
**7. USGS Quad: 1	New Castle, CC	<u>)</u>	Year: 2022	⊠ 7.5'			•	determine which fields
**8. Parcel Numbe	r: <u>2123312230</u> 1	5					are required	d, as not all locational
**9. Parcel Informa	ntion: Lot(s): <u>8, 9</u>	9	Block: 1	<u>5</u>	Addition	on: <u>ORIGIN</u>	AL TWNSTE	NEW CASTLE
**10. Acreage: <u>0.1</u>	<u>1</u>	\boxtimes ,	Actual 🗆 E	Estimated				
11. PLSS informati	ion: Principal M	eridian: <u>6th</u>	Т	ownship: <u>5S</u>		Range: 9	<u> W00</u>	
SE 1/4 of SE 1/4	of SE ¼ of NW	1 1/4 of section	n: <u>31</u>					
**12. Location Cod	ordinates:							
UTM referen	ce: Zone <u>13</u>		;mE <u>282105</u>	;mN <u>438</u>	33089	□ NAD 192	.7	⋈ NAD 1983
or								
Lat/Long: Lat	titude		; Longitude		□ V	VGS84	☐ Other:	

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls
Two-story	Edwardian	Poured concrete	Composite siding
Windows	Roof	Chimney	Porch
One-over-one double hung sash; one-over-one single hung sash; picture windows; transom	Cross gable roof clad in asphalt shingles; overhanging eaves	Brick masonry	Full length hipped roof porch along the primary (east) elevation; enclosed full-length hipped roof porch along west elevation

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The two-story, irregular shaped building was constructed circa 1904 as shown through review of a 1904 *Sanborn Fire Insurance* map. The approximately 52' by 38' building is representative of an Edwardian style of architecture. Architectural features of the building include a poured concrete foundation; a cross gable roof clad in asphalt shingles; overhanging eaves; an exterior envelop clad in composite siding; a brick masonry chimney; and a partial length protected porch along primary (south) elevation. The typical window consists of a vinyl one-over-one double hung sash. Additional windows throughout the building consist of one-over-one single hung sash and picture windows. The main entryway is located on the far-left side of the primary (east) elevation and incorporates a wood panel door that is capped by a transom. The main entryway is fronted by a partial length hipped roof porch. The porch is supported by several wood columns with rectangular railings. Decorative rectangular spindlework can also be noticed under the hipped roof eaves. A secondary entryway is located within the enclosed porch along the west elevation. The entryway consists of a wood door with 9-lite

Site #: 5GF.5900

Page 2 of 10

window divided by muntins. The enclosed porch features decorative faux support columns and rectangular spindlework. Decorative wrought iron fencing is also present along the south elevation of the building.

Historic imagery of the residence in the late Twentieth Century demonstrates that the building maintained a majority its historic windows. In addition, the partial length porch along the primary (east) elevation demonstrates that it incorporated decorative spindlework under the hipped roof eaves and turned spindle support columns. Historical street imagery from 2012 to 2022 demonstrates that a majority of windows were replaced with vinyl units, aside from two, multi-lite windows located on the north elevation. The decorative turned spindle columns and spindle work within the full-length porch along the primary (east) elevation were replaced by rectangular posts and spindlework. Faux support columns and rectangular spindlework were added to the full-length porch of the west elevation. Furthermore, a 1904 Sanborn Fire insurance map demonstrates that a shed and outbuilding were present to the north of the residence at the time of its construction. By the late Twentieth Century, the shed and outbuilding were razed.

14. Associated buildings, features, or objects:

An outbuilding is located to the north of the residence as was constructed in 2016 as shown through review of historical aerial imagery. The approximate 14' by 10' building features gambrel gable roof clad in corrugated metal; a exterior envelope clad in horizontal weatherboard; and a main entryway located along the primary (east) elevation.

A detached garage is located to the northeast of the residence. The approximately 20' by 20' building was constructed circa 2020 as shown through review of historical aerial imagery. The building features a poured concrete foundation; a front gable roof clad in corrugated metal; and a corrugated metal exterior envelope. The west elevation has several license plates that are mounted to the exterior walls.

15. Landscape (importan	t features of th	ne immediate	environment):						
□ Garden □ Mature Pla	intings 🗆 Des	signed Landso	cape Walls	□ Parki	ing Lot	t ⊠ Driveway □ Si	dewalk	⊠ Fence	□ Seating
☐ Other:									
HISTORICAL ASSOCIA	TIONS (based	l on visual obs	ervations and/o	r reviev	v of se	condary sources):			
16. Historic Function/Use	: Residential		(Current	Functi	ion/Use (if different):	Resider	<u>ntial</u>	
17. Date of Construction:	<u>1904</u>			⊠ Estin	nated	☐ Actual (include	source):	1904 San	born Fire
Insurance map									
18. Other Significant Date									
however, the building is r massing since its constru		sanborn Fire II	nsurance maps	untii 19	04. IN	e residence appears	s to mair	itain its lay	out and
19. Associated NR Areas		·e·							
☐ Agriculture	or Organicalic	□ Economic	c		□ Inv	ention		☐ Politics	s/Gov't
□ Agriculture □ Architecture		☐ Education	_			ndscape Architecture	-	□ Religio	
☐ Archaeology		☐ Engineerii			□ Lav	•		□ Science	
☐ Art		0	nent/Recreation		☐ Lite	erature		☐ Social	History
☐ Commerce		☐ Ethnic He	ritage		☐ Ma	ritime History		☐ Transp	ortation
□ Communications		☐ Exploratio	n/Settlement		☐ Mili	itary		\square Other	
□ Community Planning	& Dev't	☐ Health/Me	edicine		☐ Per	rforming Arts			
□ Conservation		\square Industry			☐ Phi	ilosophy			
Associated Historic C to have indoor plumbing.	ontext(s), if kr	nown: Accordi	ng to New Castl	e Muse	um red	cords, the residence	is the fir	st house in	า New Castle
21. Retains Integrity of:		⊠ Setting	☐ Materials	□ De	sign	☐ Workmanship	⊠ Ass	sociation	☐ Feeling

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

Site #: 5GF.5900

Page 3 of 10

23. Sources:

"644 West Main Street." Garfield County Assessor's Office. Parcel Number 212331223015. Accessed February 28, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=631205670&Key Value=R380179.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed February 28, 2023. https://act.garfield-county.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.

"Historical Aerial Imagery." NETROnline. Accessed February 28, 2023. https://www.historicaerials.com.

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/our-history.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.

Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Feb. 1893. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_001/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Nov. 1899. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_002/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, May 1904. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052 003/.

SKETCH PLAN include approximate scale

FIELD ELIGIBILITY
RECOMMENDATION:
(To be completed by surveyor)

- $\hfill\square$ Determined Eligible NR
- ☐ Determined Eligible SR
- ☑ Eligible District Contributing
- ☐ Needs Data
- ☐ Local Landmark

RECORDING INFORMATION

Survey Date: <u>9/6/2022</u>


Surveyed By: Cameron Weishoff

Project Sponsor: Town of New


Castle

Photograph Log: <u>5GF.5900_1 to</u> 5GF.5900_5, 1 historic photo, and

2 reference photos




Sketch Map



Document Path Chasershowed Destrop Kauth New Casaleh Baron 1912 156001 New Casale Historic Survey 122 156001 New Casale Historic Survey aprix

Topographic Map



Site Photographs



Photo Number: 5GF.5900_1

Description: Looking at the south and primary (east) elevations of the building. Note the decorative wrought iron fence in front of the residence.

Date: 9/6/2022 View: Northwest




Photo Number: 5GF.5900_2

Description: Looking at the south and primary (east) elevations of

the building. **Date:** 9/6/2022 **View:** Northwest

OAHP Site #: 5GF.5900 OAHP Form #1417

Site #: 5GF.5900

Page 8 of 10



Photo Number: 5GF.5900_3

Description: Looking at the west and south elevations of the

building. **Date**: 9/6/2022 **View**: Northeast



Photo Number: 5GF.5900_4
Description: Looking at the west elevation of the building.

Date: 9/6/2022 **View**: East

OAHP Site #: 5GF.5900 OAHP Form #1417


Site #: 5GF.5900 Pa

Page 9 of 10

Photo Number: 5GF.5900_5

Description: Looking at the north elevation of the building.

Date: 9/6/2022 View: Southeast





Historic Photo 1

Description: Image label states, "Smith House/First House to have indoor plumbing. 644 West Main Street." Note the turned spindles and spindlework within the porch.

Date: Unknown

Source: New Castle Museum

Collection

Site #: 5GF.5900


Page 10 of



Description: 1899 Sanborn Fire Insurance map demonstrating that the current residence was not extant at the time. The property is outlined in red.

Date: 1899

Source: Library of Congress



Reference Photo 2

Description: 1904 Sanborn Fire Insurance map of the resource located on lots 8 and 9 of block 15. The property is outlined in red.

Date: 1904

Source: Library of Congress