COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP Historical / Architectural Properties: Intensive Level / Evaluation form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)					
Da	ite:	Initials:			
	Determined Eligible	e – NR			
	Determined Eligible	e – SR			
	Needs Data				
	Eligible District - Co	ontributing			

IDENTIFICATION

1. Property Name: Engelbert Residence 🛛 Historic 🖾 Current 🗆 Other:								
2. Resource Class	ification:	Building	□ Structure	Object	Object 🛛 Sites/Landscape			
3. Ownership:	Federal	□ State	Local	🗆 Non-profit	⊠ Private			
LOCATION 4. Street Address: <u>752 West Main Street</u>								
5. Municipality: Ne	ew Castle, CO			□ Vicinity:				
6. County: <u>Garfield</u> **7. USGS Quad: <u>New Castle, CO</u> **8. Parcel Number: <u>212331224009</u>			⊠ 7.5'	 ∑ 7.5' **Please check with your project sponsor to determine which field are required, as not all locational 				
			Plook: 16					
**9. Parcel Informa			Block: <u>16</u>			<u>AL TWNSTE NEW CASTLE</u>		
**10. Acreage: 0.1	<u>1</u>	XA	Actual 🗆 Es	stimated				
11. PLSS informati	11. PLSS information: Principal Meridian: 6 th Township: 5S Range: 90W							
<u>SE</u> ¼ of <u>SW</u> ¼ of <u>SE</u> ¼ of <u>NW</u> ¼ of section: <u>31</u>								
**12. Location Coordinates:								
UTM referen	ce: Zone <u>13</u>		mE <u>282013</u>	;mN <u>43830</u>	<u>91</u> 🗆 NAD 192	7 🛛 🖾 NAD 1983		
or								
Lat/Long: Lat	titude		; Longitude		□ WGS84	□ Other:		

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls
1.5-story	Rustic	Stacked stone/concrete	Stone masonry; stone masonry belt course along primary (south) elevation
Windows	Roof	Chimney	Porch
Picture windows; one-by- one sliding sash; one- over-one single hung sash; log lintels; stone masonry and log sills	Front gable roof clad in asphalt shingles; subordinate front gable and shed roofs along north elevation; open overhanging eaves; vertical log siding in the gable ends	Metal flu	Partial length front gable porch along the primary (south) elevation

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The 1.5-story, irregular shaped building was constructed in 1893 as shown through review of Garfield County Assessor's Office records. The approximately 58' by 37' building is representative of a Rustic style of architecture. The residence features stacked stone/concrete foundation; a front gable roof clad in asphalt shingles; subordinate front gable and shed roofs along north elevation; open overhanging eaves; vertical log siding in the gable ends; an exterior envelope clad in stone masonry; a stone masonry belt course along primary (south) elevation; and a partial length front gable porch along the primary (south) elevation. The typical window consists of a one-by-one sliding sash. Additional windows throughout the residence include picture windows and one-over-one single hung sashes. Several windows also feature log lintels and stone masonry and log sills. The main entryway is located in the center of the primary (south) elevation of the building. The main door consists of a 10-lite wood door divided by muntins. The main entryway is capped by a front gable overhang. Picture windows can be noticed on both sides of the main entryway along the façade. A stone

masonry belt course and a log exterior wall can be noticed in the gable end. A subordinate front gable and several shed roof additions are evident on the north election. A double slide door is located on the far-left side often north elevation.

Sanborn Fire Insurance maps from 1893 to 1904 demonstrate that the residence consisted of a smaller layout when it was constructed. Historical aerial imagery demonstrates that a subordinate front gable addition was constructed along the north elevation by 1960. Several decades later between 1982 and 1993, additional aerial imagery reveals that a shed roof addition was constructed along the north elevation. A historic photo of the residence during the same period also shows that several windows were replaced such as the one-over-one single hung sash in the gable end along the primary (south) elevation. Between 2008 and 2012, fencing along the east elevation was moved closer to the far-left side of the east elevation. The roof has also been replaced at some point.

14. Associated buildings, features, or objects: N/A

15. Landscape (important features of the immediate environment):

\Box Garden	\boxtimes Mature Plantings	\Box Designed Landscape	\Box Walls	\Box Parking Lot	Driveway	\boxtimes Sidewalk	\Box Fence	\Box Seating
Other:								

HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources):

16. Historic Function/Use: Residential				Current Function/Use (if different): Residential				
17. Date of Construction: <u>1893</u> <u>Assessor's Office</u>				Estimated	\boxtimes Actual (include s	source): <u>Garfield (</u>	<u>County</u>	
18. Other Significant Date	es, if any: <u>N/A</u>							
19. Associated NR Areas	of Significand	ce:						
□ Agriculture		Economic	S	🗆 Inv	rention	Politic	s/Gov't	
☑ Architecture		Education	1	🗆 La	ndscape Architecture	e 🛛 🗆 Religio	on	
Archaeology		🗆 Engineeri	ng	🗆 La	w	□ Science		
□ Art		Entertainr	ment/Recreation	🗆 Lite	erature	Social History		
Commerce		🗆 Ethnic He	ritage	Maritime History		🗆 Trans	Transportation	
Communications		Exploration	on/Settlement	🗆 Mil	itary	□ Other		
Community Planning	& Dev't	□ Health/Me	edicine	🗆 Pe	rforming Arts			
□ Conservation		Industry		🗆 Ph	ilosophy			
20. Associated Historic Co	ontext(s), if kr	nown: N/A						
21. Retains Integrity of:	☑ Location	Setting	□ Materials	🗆 Design	□ Workmanship	☑ Association	Feeling	

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

23. Sources:

"752 West Main Street." Garfield County Assessor's Office. Parcel Number 212331224009. Accessed March 2, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=657093235&Key Value=R380242.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed March 2, 2023. https://act.garfieldcounty.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.

"Historical Aerial Imagery." NETROnline. Accessed March 2, 2023. https://www.historicaerials.com.

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/ourhistory. McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.

Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.


Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Feb. 1893. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_001/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Nov. 1899. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_002/.


Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, May 1904. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_003/.

 \mathbf{A}

SKETCH PLAN include approximate scale




Sketch Map



Document Path C/Usershowes/Desitop/CUU/New Castel/Batch II/122/56001 New Caste Historic Survey/122/56001 New Caste Historic Survey/aprx

Topographic Map




Document Path C/Usershowes/Desitop/CUU/New Castel/Batch IV 12156001 New Caste Hustonic Survey/122156001 New Caste Hustonic Surveyapro

Site Photographs



Photo Number: 5GF.5894_1 Description: Looking at the primary (south) elevation of the building. Date: 9/6/2022 View: North

Photo Number: 5GF.5894_2 Description: Looking at the primary (south) and east elevations of the building. Date: 9/6/2022 View: Northwest



OAHP Form #1417

Site #: 5GF.5894 Page 8 of 10

Reference Photo 1

Description: Looking at the primary (south) and east elevations of the building.

Date: 1985

View: Garfield County Assessor's Office

Reference Photo 2

Description: Looking at the primary (south) and east elevations of the building.

Date: circa 2009

Source: Garfield County Assessor's Office




OAHP Form #1417

Site #: 5GF.5894 Page 9 of 10

Reference Photo 3

Description: Looking at the east and north elevations of the building.Date: 2010View: Garfield County Assessor's Office



Reference Photo 4

Description: 1893 Sanborn Fire Insurance map illustrating residence on lots 10 and 9 of block 16. The property is outlined in red. Date: 1893 Source: Library of Congress

OAHP Form #1417 Page 10 of Site #: 5GF.5894


10

* V + V + V ^{6.} 16 ^H 6 9 10 7 в 12 13 D 10 D \mathcal{D} D 415 4/2 413 414 411 410 406 407 408 409 5 W.Pipe -------=

Reference Photo 5

Description: 1899 Sanborn Fire Insurance map of the resource. The property is outlined in red. Date: 1899

Source: Library of Congress



Reference Photo 6

Description: 1904 Sanborn Fire Insurance map of the resource. The property is outlined in red. Date: 1904 Source: Library of Congress