COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP Historical / Architectural Properties: Intensive Level / Evaluation form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)					
Da	ite:	Initials:			
	Determined Eligible -	- NR			
	Determined Eligible -	- SR			
	Needs Data				
	Eligible District - Con	tributing			

IDENTIFICATION

1. Property Name: <u>Auslander Residence</u>							
2. Resource Class	ification: 🛛 🖾 E	Building	□ Structure	Object	□ Sites/Lands	cape	
3. Ownership:	Federal	□ State	🗆 Local	🗆 Non-profit	Private		
LOCATION 4. Street Address:	792 West Main	Street					
5. Municipality: Ne	ew Castle, CO			□ Vicinity:			
6. County: <u>Garfield</u> **7. USGS Quad: <u>I</u>	New Castle, CO		Year: <u>2022</u>	⊠ 7.5'		**Please check with your project sponsor to determine which fields are required, as not all locational	
8. Parcel Numbe9. Parcel Information			Block: <u>16</u>	ŀ	Addition: ORIGIN	IAL TWNSTE NEW CASTLE	
**10. Acreage: 0.1	<u>0</u>	\boxtimes A	Actual 🛛 🗆 Est	imated			
11. PLSS information: Principal Meridian: 6 th Township: 5S Range: 90W SW ¼ of SW ¼ of SE ¼ of NW ¼ of section: 31 5S Starter 100 Ministration							
**12. Location Cod	ordinates:						
UTM referen or	ce: Zone <u>13</u>		mE <u>281985</u>	;mN <u>43830</u>	<u>992</u> □ NAD 192	27 🛛 🖂 NAD 1983	
Lat/Long: Lat	titude		Longitude		□ WGS84	□ Other:	

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls		
Two-story	Vernacular Queen Anne	Poured concrete	Horizontal weatherboard		
Windows	Roof	Chimney	Porch		
One-over-one single hung sash; 21-lite picture windows; casement windows; wood lintels, sills, and casings	Side gable roof clad in asphalt shingles; subordinate front gable along the north elevation; closed overhang eaves; front gable wall dormers; decorative fish scale shingles in the dormer and gable ends; decorative floral and scrollwork	Brick masonry chimney	Enclosed full-length porch along the west elevation; unprotected porch along the north elevation; partial length front gable porch along the primary (south) elevation		

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The two-story, rectangular shaped building was constructed circa 1899 as shown through review of an 1899 *Sanborn Fire Insurance* map. The approximately 52' by 38' building is a vernacular form of Queen Anne style of architecture. Architectural elements of the building include a poured concrete foundation; a side gable roof clad in asphalt shingles; a subordinate front gable along the north elevation; closed overhang eaves; front gable wall dormers; decorative fish scale shingles in the dormer and gable ends; decorative floral and scrollwork features; a brick masonry chimney; an enclosed full-length porch along the west elevation; an unprotected porch along the north elevation; and a partial length front gable porch along the primary (south) elevation. The typical window consists of a

one-over-one single hung sash. Additional windows throughout the building include 21-lite picture windows and casement windows. A majority of widows feature wood lintels, sills, and casings. The main entryway is located in the center of the primary (south) elevation. The main door consists of a wood panel door with a 9-lite window. The main entryway is capped by a front gable partial length porch. Decorative fish scale shingles can be noticed under the gable ends while decorative brackets are located under the eaves. The overhang is supported by turned spindle columns and the porch incorporates decorative railings.

Sanborn Fire Insurance maps between 1899 and 1904 demonstrate that the residence was constructed with a full-length porch along the primary (south) elevation. In addition, a smaller porch was located along the west elevation at the time. By 1995, historic photos reveal that the porch along the façade was altered into a partial length porch. Also, no decorative features are present in the front gable wall dormers wall dormers. Furthermore, a one-story addition was constructed along the west elevation. Between 1995 and 2003, fish scale shingles were added in the gable ends of the wall dormers. Garfield County Assessor's Office records also indicate that the roof was replaced in 2003. Historical street imagery reveals that decorative brackets and scrollwork were added by 2008. Several windows were replaced between 2012 and 2016.

14. Associated buildings, features, or objects:

A detached garage was constructed north of the residence in 2005 as shown through review of Garfield County Assessor's Office records. The approximately 30' by 26' building features a side gable roof clad in asphalt shingles; overhanging eaves; an exterior envelope clad in vinyl siding; a car port; and an overhead garage door.

15. Landscape (important features of the immediate environment):

Garden	\boxtimes Mature Plantings	$\hfill\square$ Designed Landscape	□ Walls	Parking Lot	Driveway	\boxtimes Sidewalk	⊠ Fence	□ Seating
□ Other:								

HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources):

16. Historic Function/Use: Residential	Current Function/Use (if different): Residential			
17. Date of Construction: <u>1899</u>	⊠ Estimated □ Actual (include source): <u>1899 Sanborn Fire</u>			

Insurance map

18. Other Significant Dates, if any: Garfield County Assessor's Office records indicate that the residence was constructed in 1893; however, the building is not extant on Sanborn Fire Insurance maps until 1899.

19. Associated NR Areas of Significa	nce:		
□ Agriculture	Economics	\Box Invention	Politics/Gov't
⊠ Architecture	Education	Landscape Architecture	Religion
Archaeology	Engineering	□ Law	□ Science
□ Art	Entertainment/Recreation	□ Literature	Social History
	Ethnic Heritage	☐ Maritime History	Transportation
Communications	Exploration/Settlement	Military	□ Other
Community Planning & Dev't	□ Health/Medicine	Performing Arts	
□ Conservation	□ Industry	Philosophy	
20. Associated Historic Context(s), if	known: N/A		

21. Retains Integrity of:	Location	Setting	Materials	🗆 Design	🛛 Workmanship	Association	🛛 Feeling
---------------------------	----------	---------	-----------	----------	---------------	-------------	-----------

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

23. Sources:

"792 West Main Street." Garfield County Assessor's Office. Parcel Number 212331224006. Accessed March 1, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1004555080&Ke yValue=R380132.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed March 1, 2023. https://act.garfield-

county.com/recorder/eagleweb/docSearch.jsp. "Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.

"Historical Aerial Imagery." NETROnline. Accessed March 1, 2023. https://www.historicaerials.com.

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/ourhistory.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.


Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008. Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Feb. 1893. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_001/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Nov. 1899. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_002/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, May 1904. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_003/.

 \mathbf{A}

SKETCH PLAN include approximate scale




Sketch Map



Document Path C/Usershowed/Desitop/CUU/New Castle/Batch II/12/156001 New Castle Historic Survey/1/2/156001 New Castle Historic Survey/aprx

Topographic Map



Site Photographs



Photo Number: 5GF.5892_1 Description: Looking at the primary (south) elevation of the building. Date: 9/6/2022 View: North



Photo Number: 5GF.5892_2 Description: Looking at the primary (south) and east elevations of the building. Date: 9/6/2022 View: Northwest



OAHP Form #1417 Page 8 of 10 Site #: 5GF.5892

Photo Number: 5GF.5892_3 **Description:** Looking at the west elevation of the building. Date: 9/6/2022

Reference Photo 1 Description: Looking at the primary (south) elevation of the building. Date: 1995 Source: Garfield County Assessor's Office



OAHP Form #1417


Site #: 5GF.5892 Page 9 of 10

Reference Photo 2

Description: Looking at the west and primary (south) elevation of the building. **Date:** 2003

Source: Garfield County Assessor's Office

Reference Photo 3 Description: Context view of the residence from Main Street. Date: circa 2016 Source: Garfield County Assessor's Office



OAHP Form #1417


Site #: 5GF.5892

Page 10 of 10

Reference Photo 4

Description: 1899 Sanborn Fire Insurance map illustrating the residence on lot 13 of block 16. The property is outlined in red. **Date:** 1899

Source: Library of Congress



Reference Photo 5

Description: 1904 Sanborn Fire Insurance map of the resource. The property is outlined in red.
Date: 1904
Source: Library of Congress