OAHP Site #: 5GF,2373 OAHP Form #1417

COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP *Historical / Architectural Properties: Intensive Level / Evaluation* form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility (OAHP use only)	determination
Date:	Initials:
□ Determined Elig□ Determined Elig□ Needs Data□ Eligible District	gible – SR
Lilgible District	- Contributing

DE	NIT	~	T	\mathbf{a}	N
IDE	NI	L.	١ı	u	N

1. Property Name: Mattivi Motor Co./Phillips 6	⊠ Historic ⊔ Current ⊔ Other:			
2. Resource Classification: ⊠ Building	☐ Structure	□ Object	☐ Sites/Landso	cape
3. Ownership: \square Federal \square State	☐ Local	\square Non-profit		□ Unknown
LOCATION 4. Street Address: 298 West Main Street				
5. Municipality: New Castle, CO		☐ Vicinity:		
6. County: <u>Garfield</u> **7. USGS Quad: <u>New Castle, CO</u> **8. Parcel Number: <u>212331108013</u>	Year: <u>2022</u>	⊠ 7.5'		**Please check with your project sponsor to determine which fields are required, as not all locational
**9. Parcel Information: Lot(s): <u>8-9</u>	Block: C	,	Addition: <u>ORIGIN</u>	AL TWNSTE NEW CASTLE
**10. Acreage: $\underline{0.11}$	Actual Estim	ated		
11. PLSS information: Principal Meridian: 6th SE ¼ of SW ¼ of SW ¼ of NE ¼ of section		ship: <u>5S</u>	Range: <u>9</u>	<u>90W</u>
**12. Location Coordinates:				
UTM reference: Zone 13	;mE <u>282454</u>	;mN <u>43830</u>	<u>)83</u> □ NAD 192	7 ⊠ NAD 1983
or				
Lat/Long: Latitude	; Longitude		☐ WGS84	☐ Other:

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls
One-story	Rusticated Commercial	Poured concrete	Rusticated concrete block; novelty siding; belt course
Windows	Roof	Chimney	Porch
Picture windows; three lite fixed windows divided by wood muntins; wood frames; concrete lintels and sills	Flat roof with rolled asphalt; plain coping	N/A	N/A

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The one-story, irregular plan building was constructed in 1937 as shown through review of Garfield County Assessor's Office records. The approximately 100' by 50' service station is representative of a rusticated form of Commercial style of architecture. Architectural elements of the building include a poured concrete foundation; flat roof with rolled asphalt; plain coping; plain piers; a rusticated concrete block exterior envelope; several overhead garage doors; and an angled wall main entryway. Rectangular frieze panels can also be noticed along the primary (south) elevation of the building that were formerly used for advertising and signage of the business. A decorative concrete belt course is also located in the middle of the façade of the primary (south) elevation. Novelty siding covers a former garage door opening along the primary (south) elevation. A majority of the windows feature a concrete lintel and sill. Several windows are also recessed into the exterior wall. The typical window consists of a rectangular picture window with a wood frame. There are three entryways spaced along the primary (south) elevation. The door on the far-left side of the elevation consists of a historic wood panel door while a replacement exterior door with a single lite is located in the center of the elevation. On the far-right side of the

Site #: 5GF.2373

Page 2 of 11

levitation is a large wood door with a fixed-pane window. An overhead garage door can be noticed in the center of the west elevation and is flanked by two square and two rectangular picture windows.

Historic photos demonstrate that the building's historic "Mattivi Bros. Motor Co." signage was removed by the mid to late Twentieth Century and replaced with new signage stating, "Pete Mattivi Motor Co." By 1996, this signage was also removed. At some point, the historic fuel pumps were removed and replaced. Historical aerial imagery between 1996 and 2005 demonstrates that the fuel island and replacement pumps were removed along the primary (south) elevation of the building and replaced with several trees and curb features.

14. Associated buildings, features, or	objects: N/A			
15. Landscape (important features of	the immediate environment):			
☐ Garden ☒ Mature Plantings ☐ D	esigned Landscape ☐ Walls ☐	Parking Lot □ Driveway ☒ Sid	ewalk ☐ Fence ☐ Seating	
☐ Other:		,	9	
_				
HISTORICAL ASSOCIATIONS (base	ed on visual observations and/or	review of secondary sources):		
16. Historic Function/Use: <u>Automotive</u>		•	ent): Vacant/Interior remodel	
17. Date of Construction: 1937 Assessor Office		Estimated Actual (include s	ource): Garfield County	
18. Other Significant Dates, if any: <u>Th</u> Century. Historic street imagery in 20				
19. Associated NR Areas of Significa	nce:			
☐ Agriculture	☐ Economics	☐ Invention	☐ Politics/Gov't	
	☐ Education	☐ Landscape Architecture	☐ Religion	
☐ Archaeology	☐ Engineering	□ Law	☐ Science	
☐ Art	☐ Entertainment/Recreation	☐ Literature	☐ Social History	
	☐ Ethnic Heritage	☐ Maritime History		
☐ Communications	☐ Exploration/Settlement	☐ Military	☐ Other:	
☐ Community Planning & Dev't	☐ Health/Medicine	□ Performing Arts	Association with	
☐ Conservation	☐ Industry	☐ Philosophy	Pete Mattivi	
20. Associated Historic Context(s), if Building Inventory Record by Front R			oted from the 1996 Historic	
'The building was erected in 1937 by and in 1904 as Strouse's livery. Pete board member, was born in Crystal ir help his brother Matt, in a two-stall se 19 years. Pete and Opal Mattivi own	Mattivi, a prominent citizen of Ne 1905 and lived in Marble, Salida rvice station In 1937, the broth	ew Castle who served as mayor, on a, and Glenwood Springs. He movers established this service station	county commissioner, and scho yed to New Castle in 1929 to on and also sold Studebakers for	
A historic walking tour guide by Town Cardiff [CO]."	of New Castle also states, "Mas	onry blocks for the building came	from dismantled buildings in	
21. Retains Integrity of: ⊠ Location	☐ Setting ☐ Materials	□ Design □ Workmanship	☐ Association ☐ Feeling	
22. Notes: Before the establishment of	of New Castle, the area was frequ	uented by the Ute Tribe who inhat	bited much of the mountain	

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

The resource (5GF.2373) was initially evaluated in June 1996 by Front Range Research Associates, Inc. The resource was assessed as Field – Eligible.

The Town of New Castle designated the resource as a local landmark in 2007.

Site #: 5GF.2373

Page 3 of 11

23. Sources:

"298 West Main Street." Garfield County Assessor's Office. Parcel Number 212331108013. Accessed February 16, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1737029297&KeyValue=R380286.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed February 16, 2023. https://act.garfield-county.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.

"Historical Aerial Imagery." NETROnline. Accessed December 30, 2022. https://www.historicaerials.com

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/our-history.

Front Range Associates, Inc. "Three Rivers Repair/Phillips 66 (5GF.2373)." Historic Building Inventory Record – Colorado Historical Society, June 1996.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.

Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

SKETCH PLAN include approximate scale



FIELD ELIGIBILITY RECOMMENDATION: (To be completed by surveyor)

- □ Determined Eligible NR
- oxtimes Determined Eligible SR
- ☐ Not Eligible
- ☑ Eligible District Contributing
- □ Needs Data

RECORDING INFORMATION


Survey Date: <u>9/6/2023</u>

Surveyed By: Cameron Weishoff

Project Sponsor: Town of New

Castle

Photograph Log: <u>5GF.2373_1 to</u> 5GF.2373_5, 2 historic photos, and 2 reference photos




Sketch Map



Document Path Chasershowed Destrop Kauth New Casaleh Baron 1912 156001 New Casale Historic Survey 122 156001 New Casale Historic Survey aprix

Topographic Map



Site Photographs



Photo Number: 5GF.2373_1

Description: Looking at the west and primary (south) elevations of the building. Note that a majority of the primary (south) elevation is obscured by mature deciduous trees.

Date: 9/6/2022 View: Northeast



Photo Number: 5GF.2373_2

Description: Close up view of the west and primary (south) elevation of the building.

Date: 9/6/2022 View: Northeast OAHP Site #: 5GF.2373 OAHP Form #1417

Site #: 5GF.2373 Page 8 of 11



Photo Number: 5GF.2373_3 **Description**: Looking at the west and primary (south) elevation of the building.

Date: 9/6/2022 View: Northeast



Photo Number: 5GF.2373_4

Description: Looking at the far-right side of the primary (south) and a portion of the east elevations. Note the former garage door opening that was covered by the mid to late Twentieth Century.

Date: 9/6/2022 **View**: Northwest

OAHP Form #1417 OAHP Site #: 5GF.2373


Site #: 5GF.2373

Page 9 of 11

Photo Number: 5GF.2373_5 **Description**: Looking at the east elevation of the building.

Date: 9/6/2022 View: North





Historic Photo 1

Description: Looking at the west and primary (south) elevations of the building. Note that the garage opening on the far right of the primary (south) elevation was covered by this time.


Date: Circa 1980


Source: New Castle Museum

Collection

Site #: 5GF.2373

Page 10 of






Historic Photo 2

Description: Looking at the primary (south) elevation of the building.

Date: Unknown

Source: "A Walking Tour of Downtown New Castle" by the

Town of New Castle.



Reference Photo 1

Description: Looking at the west and primary (south) elevations of the building. Note the extant fuel island and Phillips 66 sign on the roof of the building.

Date: 1996

Source: 1996 OAHP Historic **Building Inventory Record**

(5GF.2373)

OAHP Site #: 5GF.2373

Site #: 5GF.2373

Page 11 of 11



