OAHP Site #: 5GF.1166 OAHP Form #1417

COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP Historical / Architectural Properties: Intensive Level / Evaluation form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility d (OAHP use only)	etermination
Date:	Initials:
☐ Determined Eligi	
☐ Needs Data☐ Eligible District -	Contributing

IDE	NT	IFI	CA	TI	0	N

1. Property Name: Barry Building			oric 🗆 Currer	nt 🗆 Other:
2. Resource Classification: ⊠ Building	☐ Structure	☐ Object	☐ Sites/Lands	cape
3. Ownership: \square Federal \square Sta	ate 🗆 Local	☐ Non-profit		□ Unknown
LOCATION				
4. Street Address: <u>502 West Main Street</u>				
5. Municipality: New Castle, CO		☐ Vicinity:		
6. County: Garfield				**Please check with your project
**7. USGS Quad: New Castle, CO	Year: 2022	⊠ 7.5'		sponsor to determine which fields
**8. Parcel Number: 212331222019				are required, as not all locational
**9. Parcel Information: Lot(s): 1, 2	Block: <u>8</u>	,	Addition: <u>ORIGIN</u>	IAL TWNSTE NEW CASTLE
**10. Acreage: <u>0.11</u>		nated		
11. PLSS information: Principal Meridian:	6 th Town	ship: <u>5S</u>	Range:	<u>90W</u>
SE 1/4 of SE 1/4 of SE 1/4 of NW 1/4 of se	ection: <u>31</u>			
**12. Location Coordinates:				
UTM reference: Zone 13	;mE <u>282249</u>	;mN <u>43830</u>	<u>086</u> □ NAD 192	27 ⊠ NAD 1983
or				
Lat/Long: Latitude	; Longitude		☐ WGS84	☐ Other:

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls
Two-story	Nineteenth Century Commercial	Stacked stone	Brick masonry; board and batten; brick belt course under cornice; stucco on west elevation
Windows	Roof	Chimney	Porch
One-over-one single hung sash; picture windows; transom; bay window with hipped roof; segmental arches with dentils and corbelled brick features; stone sills	Flat roof with stepped parapets; corbelled brick cornice; small metal shed roof overhand along the primary (south) elevation	Stucco chimney	N/A

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The two-story, rectangular shaped building was constructed circa 1893. The approximately 78' by 46' building is representative of a Nineteenth Century Commercial style of architecture. The building features a stacked stone foundation; a flat roof with parapets; an exterior envelope clad in brick masonry, and board and batten; stucco along the west elevation; a corbelled brick cornice; segmental arches with dentils and corbelled brick features; stone masonry window sills; a brick belt course; a bay window; a stucco chimney; and cast iron pilasters with floral capitals. The typical window consists of a wooden one-over-one single hung sash. Many windows also incorporate a segmental arch lintel with dentil and corbelled brick features, and a stone masonry sill. The main entryway is located within the angled storefront on the far-right side of the primary (south) elevation of the building. The main entryway consists of a metal

Site #: 5GF.1166

Page 2 of 11

door with a single rectangular lite. The main door is capped by a single-lite transom. A bay window with typical window units is located above the main entryway on the second floor. The first floor is primarily clad in board and batten siding along the primary (south) and east elevations. A second and third entryway can be noticed on the far-left side of the primary (south) elevation. Between the cornice and the lintels of the second-floor windows on the primary (south) elevation, painted signage stating, "The Elk Creek Mining Co. Bar & Grill" can be seen. In addition, decorative dentil features can be noticed between the first and second floors of the primary (south) elevation.

Historic imagery of the building between 1900 and 1905 shows that the primary (south) elevation underwent limited change at the time. By the late Twentieth Century, additional imagery reveals that a bay window was constructed above the main entryway. Awnings were also added above windows on the first floor of the primary (south) elevation. Several windows along the first floor of the east elevation had been removed and the openings covered by brick masonry. Historic street imagery between 1996 and 2008 reveals that the exterior wall of first floor of the east and primary (south) elevation was clad in board and batten siding. In addition, windows were replaced with multi-lite picture windows. The main entryway was also replaced along with the transom. At some point, stucco was added to the exterior wall of the west elevation.

HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources): 16. Historic Function/Use: Commercial 17. Date of Construction: 1893 Sestimated Actual (include source): 1996 OAHP Historic Suilding Inventory Record (5GF.1166) Suilding Inventory Record (5GF.1166) Suilding Inventory Record (5GF.1166) Suilding Inventory Record (5GF.1166) Agriculture Economics Invention Politics/Gov't Agriculture Education Landscape Architecture Religion Archaeology Engineering Law Science Art Entertainment/Recreation Literature Social History Commerce Ethnic Heritage Maritime History Transportation Communications Exploration/Settlement Military Other Conservation Industry Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line. Prospering Barry built this 'fine brick clock ow stories with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	14. Associated buildings, features, or o	objects: N/A				
Current Function/Use (if different): Commercial Contact (include source): 1996 OAHP Historic Condition Inventory Record (Invention		·	□ Parking Lot □ Driveway □ Sid	dewalk □ Fence □ Seating		
Sestimated Actual (include source): 1996 OAHP Historic	HISTORICAL ASSOCIATIONS (base	d on visual observations and/o	r review of secondary sources):			
Building Inventory Record (5GF.1166) 18. Other Significant Dates, if any: 19. Associated NR Areas of Significance: Agriculture	16. Historic Function/Use: <u>Commercia</u>	<u>l</u> (Current Function/Use (if different):	<u>Commercial</u>		
Agriculture	17. Date of Construction: <u>1893</u> Building Inventory Record (5GF.1166)		☑ Estimated ☐ Actual (include source): 1996 OAHP Historic			
□ Agriculture □ Economics □ Invention □ Politics/Gov't □ Architecture □ Education □ Landscape Architecture □ Religion □ Archaeology □ Engineering □ Law □ Science □ Art □ Entertainment/Recreation □ Literature □ Social History □ Commerce □ Ethnic Heritage □ Maritime History □ Transportation □ Communications □ Exploration/Settlement □ Military □ Other □ Community Planning & Dev't □ Health/Medicine □ Performing Arts □ Conservation □ Industry □ Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: □ This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock ow so stories with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	18. Other Significant Dates, if any:					
Architecture	19. Associated NR Areas of Significan	ce:				
□ Archaeology □ Engineering □ Law □ Science □ Art □ Entertainment/Recreation □ Literature □ Social History □ Commerce □ Ethnic Heritage □ Maritime History □ Transportation □ Communications □ Exploration/Settlement □ Military □ Other □ Community Planning & Dev't □ Health/Medicine □ Performing Arts □ Conservation □ Industry □ Philosophy □ Description □ Philosophy □ Description □ Philosophy □ Description □ Performing Arts □ Conservation □ Industry □ Philosophy □ Description □ Performing Arts □ Conservation □ Industry □ Philosophy □ Description □ Performing Arts □ Performing Arts □ Philosophy □ Description □ Performing Arts □ Philosophy □ Description □ Performing Arts □ Philosophy □ Description □ Performing Arts □ Performing Arts □ Philosophy □ Description □ Performing Arts □ Philosophy □ Description □ Performing Arts □ Pe	☐ Agriculture	☐ Economics	□ Invention	☐ Politics/Gov't		
□ Art □ Entertainment/Recreation □ Literature □ Social History □ Transportation □ Communications □ Exploration/Settlement □ Military □ Other □ Community Planning & Dev't □ Health/Medicine □ Performing Arts □ Conservation □ Industry □ Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of the work of the same of the same function for the building. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	⊠ Architecture	☐ Education	☐ Landscape Architecture	☐ Religion		
© Communications ☐ Exploration/Settlement ☐ Military ☐ Other ☐ Community Planning & Dev't ☐ Health/Medicine ☐ Performing Arts ☐ Conservation ☐ Industry ☐ Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: 17 This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of the work of the same function for the building. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	☐ Archaeology	☐ Engineering	□ Law	☐ Science		
□ Community Planning & Dev't □ Health/Medicine □ Performing Arts □ Conservation □ Industry □ Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of the same with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	☐ Art	☐ Entertainment/Recreation	☐ Literature	☐ Social History		
☐ Conservation ☐ Health/Medicine ☐ Performing Arts ☐ Conservation ☐ Industry ☐ Philosophy 20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of two stories with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	⊠ Commerce	☐ Ethnic Heritage	☐ Maritime History	☐ Transportation		
Conservation	☐ Communications	☐ Exploration/Settlement	☐ Military	□ Other		
20. Associated Historic Context(s), if known: The following historic context is quoted from the 1996 Historic Building Inventory Record by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of the work of the building appears of the building and Smith and Smith are sent to the sent the grocery of the building and Smith are sent to the sent the	□ Community Planning & Dev't	☐ Health/Medicine	□ Performing Arts			
by Front Range Research Associates, Inc.: This building appears on the 1893 Sanborn map of New Castle and is indicated as a 'general merchandise' establishment. The 1899 and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock or wo stories with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."	☐ Conservation	☐ Industry	☐ Philosophy			
and 1904 maps give the same function for the building. Daniel Barry was the original owner of the building. Barry was described as 'a gentleman who has a prosperous business in the grocery, dry goods, boot and shoe line.' Prospering, Barry built this 'fine brick clock of the swo stories with a basement 50' X 75' at a cost of \$9,000. Barry operated his business here until 1897. Cohn, Doll & Co. (later Doll Bros. and Smith) operated a dry goods and general merchandise store here, followed by the Rocky Mountain Stores Co. from 1908-15 Albert Nelson and Joe Brunetti later operated a garage and filling station in the building through the 1940s. More recently, the building has housed a pool hall on the first floor with apartments above. Today the building is used as restaurant, La Loma West."			ontext is quoted from the 1996 Hist	toric Building Inventory Record		
	and 1904 maps give the same function gentleman who has a prosperous busing two stories with a basement 50' X 75' Bros. and Smith) operated a dry goods Albert Nelson and Joe Brunetti later openas housed a pool hall on the first floo	n for the building. Daniel Barry ness in the grocery, dry goods at a cost of \$9,000. Barry opers and general merchandise stoperated a garage and filling star with apartments above. Toda	was the original owner of the build by, boot and shoe line.' Prospering, leated his business here until 1897. Fore here, followed by the Rocky Montaion in the building through the 194 by the building is used as restauran	ling. Barry was described as 'a Barry built this 'fine brick clock o Cohn, Doll & Co. (later Doll buntain Stores Co. from 1908-15 40s. More recently, the building it, La Loma West."		

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

Site #: 5GF.1166

Page 3 of 11

The resource (5GF.1166) was initially evaluated in June 1996 by Front Range Research Associates, Inc. The resource was assessed Field – Not Eligible.

The Town of New Castle designated the resource a local landmark.

23. Sources:

"502 West Main Street." Garfield County Assessor's Office. Parcel Number 212331222019. Accessed February 23, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1729488739&KeyValue=R380283.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed February 23, 2023. https://act.garfield-county.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.

"Historical Aerial Imagery." NETROnline. Accessed February 23, 2023. https://www.historicaerials.com.

"Main Street in New Castle." Denver Public Library – Digital Collections. Accessed February 23, 2023.

https://digital.denverlibrary.org/digital/collection/p15330coll22/id/11730/rec/397.

"New Castle, Colo." Denver Public Library - Digital Collections. Accessed February 23, 2023.

https://digital.denverlibrary.org/digital/collection/p15330coll22/id/6554/rec/386.

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/our-history.

Front Range Associates, Inc. "La Loma West Restaurant – Barry Block (5GF.1166)." Historic Building Inventory Record – Colorado Historical Society, June 1996.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.


Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Feb. 1893. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_001/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, Nov. 1899. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_002/.

Sanborn Fire Insurance Map of New Castle, Garfield County, Colorado. Sanborn Map Company, May 1904. Accessed February 17, 2023. https://www.loc.gov/item/sanborn01052_003/.

SKETCH PLAN include approximate scale



- □ Determined Eligible NR
- oxtimes Determined Eligible SR
- ☐ Not Eligible
- ☑ Eligible District Contributing
- □ Needs Data

RECORDING INFORMATION


Survey Date: <u>9/6/2022</u>

Surveyed By: Cameron Weishoff


Project Sponsor: Town of New

Castle

Photograph Log: <u>5GF.1166_1 to</u> 5GF.1166_2, 2 historic photos, and 5 reference photos




Sketch Map



Document Pach ChusershoweshDesktophCutthNew CastlehBatch II 122154001 New Castle Historic Survey/122154001 New Castle Historic Surveyaprix

Topographic Map



OAHP Site #: 5GF.1166 OAHP Form #1417

Site #: 5GF.1166 Page 7 of 11

Site Photographs



Photo Number: 5GF.1166_1

Description: Looking at the primary (south) and east elevations of the building.

Date: 9/6/2022 View: Northwest



Photo Number: 5GF.1166_1


Description: Looking at the west and primary (south) elevation of

Date: 9/6/2023 View: Northeast

the building.

OAHP Site #: 5GF.1166 OAHP Form #1417

Site #: 5GF.1166 Page 8 of 11



Historic Photo 1

Description: Image of downtown New Castle looking west down Main Stret from the intersection of Main Street and North 4th Street. The resource is outlined in red.

Date: 1905

Source: Denver Public Library – Digital Collections [Not for

publication]



Historic Photo 2

Description: Image of downtown New Castle looking east down Main Stret from the intersection of Main Street and North 6th Street. The resource is outlined in red.

Date: Circa 1900-1905

Source: Denver Public Library – Digital Collections [Not for

publication]

OAHP Site #: 5GF.1166 OAHP Form #1417

Site #: 5GF.1166 Page 9 of 11

ļ.



Reference Photo 1

Description: Image states, "Laloma Resturant was Doll Bros. & Rocky Mountain store. It was also the Brunetti Garage. Now Elk Creek Mining Co."

Source: New Castle Museum

Collection



Reference Photo 2

Description: Looking at the primary (south) and east elevations of the building.

Date: 1996

Source: 1996 OAHP Historic Building Inventory Record

(5GF.1166)

Site #: 5GF.1166


Page 10 of 11



Description: 1893 Sanborn Fire Insurance map of the resource located on lots 1 and 2 of block 8. The property is outlined in red.

Date: 1893

Source: Library of Congress



Reference Photo 4

Description: 1899 Sanborn Fire Insurance map of the resource. The property is outlined in red.

Date: 1899

Source: Library of Congress

OAHP Site #: 5GF.1166

Site #: 5GF.1166

Page 11 of 11

Olic #: 001 :1100

Reference Photo 5

Description: 1904 Sanborn Fire Insurance map of the resource. The property is outlined in red.

Date: 1904

Source: Library of Congress

