COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP *Historical / Architectural Properties: Intensive Level / Evaluation* form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)					
Da	Initials:				
	Determined Eligible	e – NR			
	Determined Eligible	e – SR			
	Needs Data				
	Eligible District - Co	ontributing			

IDENTIFICATION 1. Property Name: Emily & Nathaniel Hodge Residence □ Historic ⊠ Current □ Other: □ Object 2. Resource Classification: ⊠ Building □ Structure □ Sites/Landscape 3. Ownership: □ Federal □ State Local □ Non-profit ☑ Private Unknown LOCATION 4. Street Address: 281 East Main Street 5. Municipality: New Castle, CO □ Vicinity: 6. County: Garfield **Please check with your project sponsor to determine which fields **7. USGS Quad: New Castle, CO Year: 2022 ⊠ 7.5' are required, as not all locational **8. Parcel Number: 212331405001 **9. Parcel Information: Lot(s): 1-4 Block: P Addition: Spencer's 2nd ⊠ Actual Estimated **10. Acreage: 0.24 11. PLSS information: Principal Meridian: 6th Township: 5S Range: 90W NW ¼ of NW ¼ of NE ¼ of SE ¼ of section: 31 **12. Location Coordinates: ;mN <u>4383017</u> 🗆 NAD 1927 UTM reference: Zone 13 ;mE <u>282746</u> X NAD 1983 or Lat/Long: Latitude ; Longitude _____ UWGS84 □ Other:

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls		
One-story	No Style	Concrete (faux stone masonry)	Horizontal weatherboard		
Windows	Roof	Chimney	Porch		
One-by-one sliding sash with vinyl frame; three-lite sliding sash with metal frame; picture window with wood frame; one-over-one double hung sash with wood frame	Front gable roof; asphalt shingles; lower shed roof transitions; closed overhanging eaves; attic vent under the gable peak	Stone masonry chimney	Partial length elevated deck located along the west elevation; full length elevated deck along the south elevation		

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The one-story, irregular shaped building was constructed in 1938 as shown through review of Garfield County Assessor's Office records. The approximately 50' by 40' residence does not represent a particular architectural style. Overall, the building is a No Style residence. Architectural features of the building include a concrete foundation with faux stone masonry; an exterior envelope clad with horizontal weatherboard; a front gable roof design; asphalt shingles; lower shed roof transitions along both west and east elevations; an attic vent underneath the gable peak; closed overhanging eaves; a stone masonry chimney; a partial length elevated deck along the west elevation; and a full-length elevated deck along the south elevation. The main entryway is located near the center of the primary (north) elevation and under the front gable end. The main entryway incorporates a metal panel door with a sunburst window. Additionally, there are entryways located along the east, west, and south elevations. The typical window consists of a one-by-one

sliding sash unit with a vinyl frame. Other windows found throughout the residence include three-lite sliding sash units with metal framing; picture windows with wood framing; and one-over-one double hung sash with wood framing. Historical aerial imagery demonstrates that an addition was constructed along the left side of the south elevation between 1960 and 1982.

14. Associated buildings, features, or objects:

A detached garage is located to the east of the residence. It is unclear in the historic record when the building was constructed; however, historical aerial imagery demonstrates it was present by 1960. The building is approximately 50' by 25' and features a concrete foundation; a front gable roof clad in asphalt shingles; overhanging eaves; concrete masonry unit (CMU) exterior envelope; and two garage doors along the primary (north) elevation. The typical window consists of a one-by-one sliding sash. Three of these typical windows can be noticed along the east elevation. Four-lite picture windows can also be seen along the south elevation. An entryway is located on the west elevation.

15. Landscape (important features of the immediate environment):

Garden	\boxtimes Mature Plantings	□ Designed Landscape	\Box Walls	Parking Lot	🛛 Driveway	\boxtimes Sidewalk	□ Fence	\Box Seating
□ Other:								

HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources):

16. Historic Function/Use: <u>Residential</u>				Current Function/Use (if different): <u>Residential</u>					
17. Date of Construction: <u>1938</u> <u>Assessor's Office</u>				Estimated	\boxtimes Actual (include	source): <u>Garfield (</u>	<u>County</u>		
18. Other Significant Date	es, if any: <u>N/A</u>	<u>.</u>							
19. Associated NR Areas	of Significan	ce:							
□ Agriculture		🗆 Economic	S	🗆 Inv	rention	🗆 Politic	s/Gov't		
□ Architecture		Education	cation 🗆 Landscape A		ndscape Architecture	e 🛛 🗆 Religi	on		
Archaeology		Engineering		🗆 Lav	□ Law		□ Science		
□ Art		□ Entertainment/Recreation		n 🗆 Lite	□ Literature		Social History		
□ Commerce		🗆 Ethnic He	Ethnic Heritage		Maritime History		□ Transportation		
Communications		Exploration	on/Settlement	□ Military		□ Other			
Community Planning	& Dev't	□ Health/Me	edicine	Performing Arts					
Conservation		Industry		🗆 Ph	□ Philosophy				
20. Associated Historic C	ontext(s), if ki	nown: NA							
21. Retains Integrity of:	☑ Location	⊠ Setting	☐ Materials	🗆 Design	Workmanship	□ Association	Feeling		

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

23. Sources:

"281 East Main Street." Garfield County Assessor's Office. Parcel Number 212331405001. Accessed December 28, 2022. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1467385676&Ke yValue=R380079.

"Document Search." Garfield County Clerk and Recorder Office. Accessed December 28, 2022. https://act.garfieldcounty.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.


"Historical Aerial Imagery." NETROnline. Accessed December 28, 2022. https://www.historicaerials.com

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/ourhistory. McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.


Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

 \mathbf{A}

SKETCH PLAN include approximate scale




Sketch Map



Document Path C/Usershowed/Desitop/CUL/New Castel/Batch II 122156001 New Caste Historic Survey/122156001 New Caste Historic Surveyaprx

Topographic Map



Site Photographs



Photo Number: 5GF.5928_1 Description: Looking at the primary (north) elevation of the residence. Date: 9/6/2022 View: South

Photo Number: 5GF.5928_2 Description: Looking at the primary (north) and west elevations of the building. Date: 9/6/2022 View: Southeast

OAHP Form #1417

Site #: 5GF.5928 Page 8 of 8



Photo Number: 5GF.5928_3

Description: Looking at the west and primary (north) elevations of the building. Date: 9/6/2022 View: Southwest