# COLORADO CULTURAL RESOURCES INVENTORY

# **Historical and Architectural Reconnaissance**

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP Historical / Architectural Properties: Intensive Level / Evaluation form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer the instructions, to available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only) Date: Initials: Determined Eligible – NR Determined Eligible – SR Needs Data Eligible District - Contributing

#### **IDENTIFICATION**

DENTIFICATION								
1. Property Name: Shannon Poland & Carmel Walden Residence I Historic I Current I Other:								
2. Resource Class	ification:	Building	□ Structure	Object	cape			
3. Ownership:	Federal	□ State	🗆 Local	🗆 Non-profit	⊠ Private			
LOCATION 4. Street Address: 5. Municipality: <u>Ne</u>				□ Vicinity:				
**7. USGS Quad: <u>New Castle, CO</u>			Year: <u>2022</u>	⊠ 7.5'		**Please check with your project sponsor to determine which fields are required, as not all locational		
**8. Parcel Numbe	er: <u>2123311050</u>	<u>)11</u>				1 <i>i</i>		
**9. Parcel Informa	ation: Lot(s): <u>1-</u>	-4	Block: <u>F</u>	A	Addition: <u>Spence</u>	's Addition		
**10. Acreage: 0.22								
11. PLSS informat	ion: Principal N	/leridian: <u>6th</u>	Tow	nship: <u>5S</u>	Range: 9	90W		
<u>SW</u> ¼ of <u>SW</u> ¼ of <u>SE</u> ¼ of <u>NE</u> ¼ of section: <u>31</u>								
**12. Location Cod	ordinates:							
UTM reference: Zone <u>13</u> ;mE <u>282745</u>			;mN <u>4383074</u>					
or								
Lat/Long: La	titude		; Longitude		□ WGS84	□ Other:		

#### DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls		
One-story	No Style (some Queen Anne features)	Stacked stone	Vinyl		
Windows	Roof	Chimney	Porch		
Six-over-six double hung sash; four-over-four double hung sash; decorative shutters	Front gable roof design; boxed overhanging eaves; metal roof; front gable porch overhang	Brick masonry chimney	Partial length porch with front gable overhang along primary (south) elevation		

*Optional:* additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The one-story, rectangular shaped building was constructed in 1893 as shown through review of Garfield County Assessor's Office records. The approximately 48' by 36' primary residence does not represent a particular architectural style, although it does incorporate some elements of Queen Anne style elements. Several architectural elements of the residence consist of a stacked stone foundation; front gable roof design; metal roof; boxed overhanging eaves; an exterior envelope clad with vinyl siding; a brick masonry chimney; decorative window shutters; two bay windows; a partial length porch with front gable overhanging along the primary (south) elevation; and a shed roof addition to the north elevation. The main entryway is located in the center of the primary (south) elevation with a partial length porch along the facade as well. The entryway consists of a wood door with 12-lites divided by muntins. The main door is fronted by a metal storm door with two picture windows. The entryway is capped by a front gable overhang that protects the porch. Decorative fishscale shingles can be noticed in the gable end. The overhang is also supported by architectural support sports. Decorative wood spindlework and brackets like the ceiling of the porch overhang. Architectural porch railings are also present. Two bay windows were added at some point and are located on both left and right corners of the primary (south) elevation. The center window unit of each bay

window incorporates a typical window consisting of a six-over-six double hung sash unit. The center window of the bay unit is flanked on both sides by a four-over-four double hung sash unit. A shed roof addition was constructed along the north elevation of the building at some point. Additionally, the metal roof likely replaced a prior asphalt shingle roof.

#### 14. Associated buildings, features, or objects:

A garage is located to the northeast of the residence. It is unclear in the historic record when the garage was constructed; however, it is extant on historical aerial imagery by 1960 The garage is approximately 20' by 30' and features a front gable roof clad in metal; closed overhanging eaves; a horizontal weatherboard exterior envelope; and a garage door along the primary (east) elevation. The typical window consists of a six-by-six sliding sash. A shed roof overhang is also located along the south elevation of the building.

A secondary residence is located to the northwest of the primary residence. The approximately 30' by 66' building was constructed in 1940 as shown through review of Garfield County Assessor's Office records. The secondary residence features a poured concrete fountain; shed roof clad in metal; boxed overhanging eaves; and horizontal weatherboard siding. The typical window unit consists of a vinyl one-over-one single hung sash. The main entryway is located in the center of the primary (east) elevation.

15. Landscape (important features of the immediate environment):

Garden	□ Mature Plantings	Designed Landscape	⊠ Walls	Parking Lot	Driveway	Sidewalk	⊠ Fence	Seating
Other:								

#### HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources):

16. Historic Function/Use: <u>Residential</u>				Current Function/Use (if different): Residential						
17. Date of Construction: Assessor's Office	7. Date of Construction: <u>1893</u> ssessor's Office				□ Estimated ⊠ Actual (include source): Garfield County					
18. Other Significant Date	s, if any: <u>N/A</u>									
19. Associated NR Areas	of Significand	ce:								
□ Agriculture		Economic	S	🗆 Inv	vention	Politic	s/Gov't			
□ Architecture		Education		🗆 La	ndscape Architecture	🗆 Religi	on			
Archaeology		🗆 Engineeri	ng	🗆 La	w	🗆 Scien	се			
□ Art		Entertainr	nent/Recreatior	n 🗆 Lite	erature	🗆 Socia	Social History			
□ Commerce		🗆 Ethnic He	ritage	🗆 Ma	aritime History	🗆 Trans	portation			
Communications		Exploration	n/Settlement	🗆 Mi	litary	Other				
☑ Community Planning	& Dev't	□ Health/Me	edicine	🗆 Pe	rforming Arts					
□ Conservation		Industry		🗆 Ph						
20. Associated Historic Co	ontext(s), if ki	nown: NA								
21. Retains Integrity of:	☑ Location	□ Setting	☐ Materials	🗆 Design	Workmanship	☑ Association	⊠ Feeling			

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

#### 23. Sources:

"296 East Main Street." Garfield County Assessor's Office. Parcel Number 212331105011. Accessed December 27, 2022. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=699704662&Key Value=R380169.

"Document Search." Garfield County Clerk and Recorder Office. Accessed December 27, 2022. https://act.garfield-county.com/recorder/eagleweb/docSearch.jsp.


"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/. "Historical Aerial Imagery." *NETROnline*. Accessed December 27, 2022. https://www.historicaerials.com "Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/our-history.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.


Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

 $\mathbf{A}$ 

#### SKETCH PLAN include approximate scale




Sketch Map



Document Path C/Usershowed/Desitop/CUU/New Castle/Batch II/12/156001 New Castle Historic Survey/1/2/156001 New Castle Historic Survey/aprx

# Topographic Map



## **Site Photographs**




Photo Number: 5GF.5929\_1 Description: Looking at the primary (south) elevation of the primary building. Note the decorative wood spindlework and brackets under the gable ceiling of the porch overhang. Date: 9/6/2022

View: North



Photo Number: 5GF.5929\_2 Description: Looking at the west and primary (south) elevations of the primary residence. Date: 9/6/2022 View: Northeast

Site #: 5GF.5929 Page 8 of 9



#### Photo Number: 5GF.5929\_3

Description: Looking at the west elevation of the primary building. A majority of the elevation is obscured by vegetation. Date: 9/6/2022 View: Northeast



Photo Number: 5GF.5929\_4 Description: Looking at the east elevation of the primary building. Date: 9/6/2022 View: Northwest

Site #: 5GF.5929 Page 9 of 9

### Photo Number: 5GF.5929\_5

**Description:** Looking at the east elevation of the primary building. Note the shed roof addition to the north elevation (right side of photo).

**Date:** 9/6/2022 **View:** West