COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP *Historical / Architectural Properties: Intensive Level / Evaluation* form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)					
Da	te:	Initials:			
	Determined Eligible	e – NR			
	Determined Eligible	e – SR			
	Needs Data				
	Eligible District - Co	ontributing			

IDENTIFICATION

1. Property Name: Marquardt Residence ☐ Historic ☐ Current ☐ Other:									
2. Resource Class	ification: 🛛 🖂 B	uilding	□ Structure	Object	□ Object □ Sites/Landscape				
3. Ownership:	Federal	□ State	Local	🗆 Non-profit	⊠ Private	🗆 Unknown			
LOCATION 4. Street Address:	LOCATION 4. Street Address: <u>333 West Main Street</u>								
5. Municipality: Ne	ew Castle, CO			□ Vicinity:					
<u></u>			Year: <u>2022</u>	⊠ 7.5'		sponsor to dete	with your project ermine which fields s not all locational		
 **8. Parcel Number: <u>212331409009</u> **9. Parcel Information: Lot(s): <u>3, 4</u> Block: <u>7</u> Addition: <u>ORIGINAL TWNSTE NEW CASTLE</u> 							W CASTLE		
**10. Acreage: 0.1	**10. Acreage: 0.11								
11. PLSS information: Principal Meridian: 6 th Township: 5S Range: 90W NW ¼ of NW ¼ of SE ¼ of section: 31 Township: 5S Range: 90W									
**12. Location Coc	ordinates:								
UTM referent	ce: Zone <u>13</u>		;mE <u>282369</u>	;mN <u>43830</u>	<u>26</u>	□ NAD 1927	⊠ NAD 1983		
Lat/Long: Lat	titude		; Longitude		□ WGS84	□ Other:			

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls
1.5-story	Vernacular Queen Anne	Poured concrete	Horizontal weatherboard siding
Windows	Roof	Chimney	Porch
One-over-one single hung sash; two-over-two single hung sash; picture window; bay window; elliptical window; wooden lintel, sill, and casings	Front gable; asphalt shingles; closed overhanging eaves; decorative half cove shingles in the gable ends; pediment along north elevation	Metal flu	Particle length porch with shed roof overhang along primary (west) elevation; full length enclosed hipped roof porch and a full length deck along the south elevation

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The 1.5-story, rectangular shaped building was constructed in 1909 as shown through review of Garfield County Assessor's Office records. The approximately 54' by 34' building is a vernacular form of Queen Anne style of architecture. The residence features a poured concrete foundation; a front gable roof clad in asphalt shingles; closed overhanging eaves; an exterior envelope clad in horizontal weatherboard siding; a pediment along the north elevation; a bay window; a particle length porch with shed roof overhang along the primary (west) elevation; and a full length enclosed hipped roof porch and a full length deck along the south elevation. The typical window consists of a one-over-one single hung sash with a wood lintel, sill, and casings. However, two-over-two single hung sash; picture windows; and a bay window are also present along the exterior envelope of the building. Decorative half cove shingles can be noticed in the gable end of the north elevation. The main entryway is located along the primary (west) elevation. A bay window incorporating a center picture window flanked by typical windows is located to the left of the main entryway. Decorative panel kickplates

can be noticed below the bay window. These features are protected by a shed roof overhang to a particle length porch. The overhang is supported by architectural support columns and porch railing features architectural spindlework. A full-length enclosed porch is located along the south elevation as well as a full-length unprotected deck.

Historical aerial imagery between 1960 and 1982 demonstrates that the full-length hipped roof enclosed porch was constructed along the south elevation of the building. Historic street imagery between 2009 and 2022 reveals that three typical window units along the north elevation were placed by large picture window flanked by two-over-two single hung sash windows. At some point, the bay window was constructed along the primary (west) elevation.

14. Associated buildings, features, or objects: N/A

15. Landscape (important features of the immediate environment):

🛛 Garden	☑ Mature Plantings	Designed Landscape	□ Walls	Parking Lot	Driveway	Sidewalk	⊠ Fence	Seating
□ Other:								

HISTORICAL ASSOCIATIONS (based on visual observations and/or review of secondary sources):

16. Historic Function/Use: Residential				Current Function/Use (if different): Residential					
17. Date of Construction: <u>1909</u> Assessor's Office				□ Estimated ⊠ Actual (include source): Garfield Cour					
18. Other Significant Date	s, if any: <u>N/A</u>	1							
19. Associated NR Areas	of Significan	ce:							
□ Agriculture		🗆 Economic	s	🗆 Inv	ention	Politic	cs/Gov't		
☑ Architecture		Education	ı	Landscape Architecture		Religion			
Archaeology		🗆 Engineeri			N	□ Science			
□ Art		□ Entertainment/Recreation		n 🗆 Lite	erature	🗆 Socia	Social History		
□ Commerce		🗆 Ethnic He	eritage	□ Ma	ritime History	🗆 Trans	portation		
Communications		Exploration	on/Settlement	🗆 Mil	🗆 Other				
Community Planning	& Dev't	□ Health/Me	edicine	🗆 Pe	rforming Arts				
□ Conservation		Industry		🗆 Phi	ilosophy				
20. Associated Historic Co	ontext(s), if k	nown: N/A							
21. Retains Integrity of:	☑ Location	⊠ Setting	☐ Materials	Design	Workmanship	☑ Association	□ Feeling		

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

23. Sources:

"331 West Main Street." Garfield County Assessor's Office. Parcel Number 212331409009. Accessed February 22, 2023. https://qpublic.schneidercorp.com/Application.aspx?AppID=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1464504365&Ke yValue=R380399.

"A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed February 22, 2023. https://act.garfieldcounty.com/recorder/eagleweb/docSearch.jsp.

"Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.


"Historical Aerial Imagery." NETROnline. Accessed February 22, 2023. https://www.historicaerials.com.

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/ourhistory. McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.

Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

 \mathbf{A}

SKETCH PLAN include approximate scale




Sketch Map



Document Path C/Usershowed/Desitop/CULINew CastelBatch II 122156001 New Caste Historic Survey/122156001 New Caste Historic Surveyaprx

Topographic Map



Site Photographs



Photo Number: 5GF.5914_1 Description: Looking at the north elevation of the building. Date: 9/6/2022 View: South



Photo Number: 5GF.5914_2 Description: Looking at the north and primary (west) elevations of the building. Date: 9/6/2022 View: Southeast

Site #: 5GF.5914 Page 8 of 9



Photo Number: 5GF.5914_3

Description: Looking at the east and north elevation of the building. Date: 9/6/2022 View: Southwest



Reference Photo 1

Description: Looking at the west and north elevations of the residence. Date: Unknown Source: New Castle Museum

Collection

OAHP Form #1417

Site #: 5GF.5914 Page 9 of 9



Reference Photo 2

Description: Looking at the north and primary (west) elevations of the building.

Date: circa 2009

Source: Garfield County Assessor's Office