OAHP Site #: 5GF.5910 OAHP Form #1417

COLORADO CULTURAL RESOURCES INVENTORY

Historical and Architectural Reconnaissance

□ I linta sia

☑ Current

□ O4h o ***

This form is intended for use in survey projects undertaken for preservation planning purposes and it is NOT to be used for Section 106 compliance projects. It provides a basic descriptive record of a single building, structure, object, or site. Please use the #1417b Ancillary form to document additional resources on a single site. This form may provide enough information to assess architectural significance and/or to identify other potential areas of historical significance. Full evaluations of historical significance require additional property-specific research beyond the scope of this form and typically require completion of the OAHP Historical / Architectural Properties: Intensive Level / Evaluation form (OAHP form # 1403). For guidance on completing this form and required accompanying documentation, please refer to the instructions, available online at http://www.historycolorado.org/oahp/survey-inventory-forms

Official eligibility determination (OAHP use only)
Date: Initials:
□ Determined Eligible – NR□ Determined Eligible – SR
☐ Needs Data☐ Eligible District - Contributing

IDEN	ITI	۸ті	\sim NI
IDEI	411	~ ! !	CIN

Proporty Name: Chanin Pagidanas

i. Property Name.	Chapin Reside	ence					it 🗆 Other.	
2. Resource Classif	fication:	Building	□ Structu	re 🗆	Object	☐ Sites/Lands	cape	
3. Ownership:	□ Federal	☐ State	□ Loc	al 🗆	Non-profit	□ Private	□ Unknown	
LOCATION								
4. Street Address: 4	137 West Mair	Street						
5. Municipality: Nev	w Castle, CO				Vicinity:			
6. County: Garfield								k with your project
**7. USGS Quad: <u>N</u>	lew Castle, Co	<u>)</u>	Year: 202	<u>22</u> 🗵	7.5'		•	termine which fields as not all locational
**8. Parcel Number	: <u>2123314090</u>	<u>07</u>					are required, a	do not an locational
**9. Parcel Informat	tion: Lot(s): <u>12</u>	<u>-14</u>	Block	: <u>7</u>	A	Addition: ORIGIN	AL TWNSTE N	EW CASTLE
**10. Acreage: <u>0.17</u>	• -	\boxtimes	Actual [☐ Estimate	ed			
11. PLSS information	on: Principal M	leridian: 6 th		Township	p: <u>5S</u>	Range: 9	90W	
<u>NW</u> ¼ of <u>NW</u> ½	4 of <u>NW</u> ¼ of §	SE ¼ of secti	on: <u>31</u>					
**12. Location Coor	rdinates:							
UTM referenc	e: Zone <u>13</u>		;mE <u>28229</u>	<u>5</u>	;mN <u>43830</u>	<u>28</u> □ NAD 192	27	⋈ NAD 1983
or								
Lat/Long: Lati	tude		: Lonaitude			□ WGS84	☐ Other:	

DESCRIPTION

13. Construction Features (forms, materials):

Stories	Style/Type	Foundation	Walls	
One-story	Bungalow	Poured concrete	Vertical weatherboard/corrugated metal siding; wood shingles	
Windows	Roof	Chimney	Porch	
One-over-one single hung sash; picture window; three-lite sliding sash; wood frames; wood lintel and sills	Cross gable roof; metal roof; boxed overhanging eaves	Metal flu	Full-length front gable porch along the primary (north) elevation; particle-length unprotected wood porch along the east elevation	

Optional: additional description (plan/footprint, dimensions, character-defining and decorative elements of exterior and interior; alterations, additions, etc.):

The one-story, rectangular shaped building was constructed in 1929 as shown through review of Garfield County Assessor's Office records. The approximately 44' by 32' building is representative of a vernacular form of Bungalow type architecture. Architectural elements of the building include a poured concrete foundation; a cross gable roof clad in corrugated metal; boxed overhanging eaves; an exterior envelope clad in vertical weatherboard, corrugated metal, and wood shingles; a full-length front gable porch along the primary (north) elevation; and a particle-length unprotected wood porch along the east elevation. The top half of exterior walls consists of vertical weatherboard while the bottom half incorporates corrugated metal. The main entryway is located on the left side of the primary (north) elevation. The main door consists of a wood panel door with two divided lites. A wooden three-lite sliding sash window is located of the door and is capped by four-lites divided by muntins. These features are also located underneath a front gable overhang that protects the wood porch. In addition, the exterior wall of the north elevation is clad in wood shingles. The typical window consist of a wood one-over-one single hung sash with a wood sill, lintel, and casing. The east elevation incorporates several typical windows. A

Site #: 5GF.5910

Page 2 of 8

secondary entryway is located on the left side of the elevation underneath the gable end. The secondary door consists of a wood door with a single rectangular lite. A particle length unprotected wood patio can be noticed along the far left and center portions of the elevation. A skeleton riding a moped is mounted to the gable end.

The residence has undergone a high degree of modification since it was constructed in 1929. Historical aerial imagery demonstrates that several additions were constructed along the south elevation by 1960. Street imagery between 2012 and 2022 reveals that the residence previously incorporated horizontal weatherboard siding on all elevations; battered support columns to the front gable porch overhang along the primary (north) elevation; faux shutters along the east elevation; overhanging eaves with exposed rafter tails; a small concrete staircase along the east elevation; a wood and mesh storm door along the primary (north) elevation; and a half wall along the bottom of the porch along the façade.

14. Associated buildings, features, or c	objects: N/A			
15. Landscape (important features of tl □ Garden ⊠ Mature Plantings □ De	•	☐ Parking Lot	: □ Driveway ⊠ Sid	lewalk ⊠ Fence □ Seating
☐ Other:				
HISTORICAL ASSOCIATIONS (based	d on visual observations and/	or review of se	condary sources):	
16. Historic Function/Use: Residential			on/Use (if different):	Residential
17. Date of Construction: <u>1929</u> <u>Assessor's Office</u>		☐ Estimated		source): <u>Garfield County</u>
18. Other Significant Dates, if any: N/A	<u>.</u>			
19. Associated NR Areas of Significand	ce:			
☐ Agriculture	☐ Economics	□ Inv	ention	☐ Politics/Gov't
	☐ Education	☐ Lar	ndscape Architecture	☐ Religion
☐ Archaeology	□ Engineering	☐ Lav	V	☐ Science
☐ Art	☐ Entertainment/Recreatio	n 🗆 Lite	erature	☐ Social History
☐ Commerce	☐ Ethnic Heritage	□ Ma	ritime History	☐ Transportation
☐ Communications	☐ Exploration/Settlement	☐ Mili	itary	□ Other
☐ Community Planning & Dev't	☐ Health/Medicine	□ Per	forming Arts	
☐ Conservation	□ Industry	☐ Phi	losophy	
20. Associated Historic Context(s), if ki	nown: N/A			
21. Retains Integrity of:	☐ Setting ☐ Materials	☐ Design	☐ Workmanship	
22. Notes: Before the establishment of	New Castle, the area was fro	equented by the	e Ute Tribe who inha	bited much of the mountain

22. Notes: Before the establishment of New Castle, the area was frequented by the Ute Tribe who inhabited much of the mountain areas in western Colorado and eastern Utah throughout the summer seasons. However, the lure of wealth from natural resource extraction from several gold rushes and silver booms prompted many American settlers to explore the Rocky Mountains between the mid to late-Nineteenth Century. By 1881, the tribe had been removed from the area and relocated to the Uintah and Ouray Reservation in Utah. The Town of New Castle was incorporated several years later in 1888, shortly after Jasper Ward built the first homestead in the area in 1883. Coal mining quickly became a vital industry in the vicinity to supply fuel to silver smelters throughout the Rocky Mountain region. The town experienced several boom-and-bust cycles of the industry until the early to mid-Twentieth Century when coal mining came to a more permanent end. In the aftermath, agricultural operations including farming and ranching began to take hold throughout the mid to late-Twentieth Century due to the fertile soil in the area. Between the late-Twentieth- and early-Twenty-first Centuries, the town has experienced a sustainable growth in population.

23. Sources:

- "437 West Main Street." Garfield County Assessor's Office. Parcel Number 212331409007. Accessed February 22, 2023. https://qpublic.schneidercorp.com/Application.aspx?ApplD=1038&LayerID=22381&PageTypeID=4&PageID=9447&Q=1758861590&KeyValue=R380115.
- "A Walking Tour of Downtown New Castle." Town of New Castle. Accessed December 29, 2022.

https://www.newcastlecolorado.org/sites/default/files/fileattachments/community/page/1360/walking_tour_of_downtown_new_castle.pdf "Document Search." Garfield County Clerk and Recorder Office. Accessed February 22, 2023. https://act.garfield-county.com/recorder/eagleweb/docSearch.jsp.

- "Early History." Southern Ute Indian Tribe. Accessed December 21, 2022. https://www.southernute-nsn.gov/history/.
- "Historical Aerial Imagery." NETROnline. Accessed February 22, 2023. https://www.historicaerials.com.

OAHP Site #: 5GF.5910 OAHP Form #1417

Site #: 5GF.5910

Page 3 of 8

"Our History." Town of New Castle, Colorado. Accessed December 21, 2022. https://www.newcastlecolorado.org/about/page/our-history.

McAlester, Virginia S. A Field Guide to American Houses: The Definitive Guide to Identifying and Understanding America's Domestic Architecture. New York: Alfred A. Knopf, 2013.

Pearce, Sarah J. Field Guide to Colorado's Historic Architecture & Engineering. Denver: State Historic Society of Colorado, 2008.

SKETCH PLAN include approximate scale

FIELD ELIGIBILITY
RECOMMENDATION:
(To be completed by surveyor)

- \square Determined Eligible NR
- ☐ Determined Eligible SR
- ☐ Eligible District Contributing
- ☐ Needs Data
- ☐ Local Landmark

RECORDING INFORMATION

Survey Date: <u>9/6/2022</u>


Surveyed By: Cameron Weishoff

Project Sponsor: Town of New


Castle

Photograph Log: <u>5GF.5910_1 to</u> 5GF.5910_3, and 1 reference

photo




Sketch Map



Document Path C. Nusershowed Desitop (C.U.L.INew Castlel Batch 11/12/15600 | New Castle Historic Survey/1/12/15600 | New Castle Historic Survey aprix

Topographic Map



OAHP Site #: 5GF.5910 OAHP Form #1417

Site Photographs



Photo Number: 5GF.5910_1

Description: Looking at the primary (north) elevation of the residence.

Date: 9/6/2022 **View:** South



Photo Number: 5GF.5910_2

Description: Looking at the west elevation of the building.

Date: 9/6/2022 View: Southeast OAHP Site #: 5GF.5910

Site #: 5GF.5910

Page 8 of 8

OAHP Form #1417



Photo Number: 5GF.5910_3

Description: Looking at the east and primary (north) elevations of the

building. **Date:** 9/6/2022 **View:** Southwest



Reference Photo 1

Description: Looking at the east and primary (north) elevation of the building.

Date: Circa 2009 View: Southwest